




iRobot Roomba 960 Side-Brush Replacement

iRobot Roomba 960 Side-Brush Replacement Guide.

Written By: Romulo Duarte



INTRODUCTION

This guide will instruct you how to replace a filter in the iRobot Roomba 960. Side-Brush should be replaced often with frequent use.



TOOLS:


- [Flathead 3/32" or 2.5 mm Screwdriver](#) (1)



PARTS:


- [Roomba 800 and 900 Series Side Brush](#) (1)

Step 1 — Side-Brush



- With the Flathead 2.5mm screwdriver remove the 7.9mm screw from the side-brush.

Step 2



- Pull the side-brush towards you.
- Carefully remove the side-brush.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-10 12:55:38 PM.